ENVIRONMENTAL PROTECTION AGENCY

Generator Biennial Hazardous Waste Report for 1985 (cont.)

This report is for the calendar year ending December 31, 1985

GENERATOR'S NAME:

CARRIER CORPORATION, 1700 EAST DUNCAN STREET, TYLER, TX. 75702

Rec'd by:

XV. GENERATOR'S EPA I.D. NO.

T X D O O 7 3 3 1 1 2 7 11 1 2 13 14 15

XVI. WASTE MINIMIZATION (narrative description)

A. PAINT FILTERS

Texas Waste Code: 981350 EPA Waste Number: D001, F005

Normal processing requires those parts painted with the high solids/low solvent paint to be baked for a properly dried finish. In the wet condition the paint is classified as flammable. To eliminate the flammable characteristic associated with the wet paint, the filters are baked until dry prior to disposal with the plant refuse.

RESULTS:	YEAR	GALLONS GENERATED
	1984	27,280
	1985	9,405

B. PAINT AND SOLVENTS

Texas Waste Code: 916940 EPA Waste Number: D001

Continued improvements to the painting operation, including the use of high solids/low solvent paint and upgraded equipment, have reduced the demand for large volumes of cleaning solvents. Beginning in 1985, the waste solvents were shipped to a solvent reclaiming/recycling facility as compared to landfilling in 1984.

RESULTS:	YEAR	GALLONS GENERATED
	1984	6,490
	1985	2,970

C. TRICHLOROETHYLENE IN OIL Texas Waste Code: 911870

EPA Waste Number: F001

The use of trichloroethylene as a degreaser was discontinued in September, 1985. Removal and consequent disposal of all trichloroethylene waste continued through 1985 and was completed in 1986.

RESULTS:	YEAR	GALLONS GENERATED
	1984	10,230
	1985	5,500

car out here

Do not make entries in shaded areas

ENVIRONMENTAL PROTECTION AGENCY

Generator Biennial Hazardous Waste Report for 1985 (cont.)

This report is for the calendar year ending December 31, 1985

GENERATOR'S NAME:

CARRIER CORPORATION, 1700 EAST DUNCAN STREET, TYLER, TX. 75702

Rec'd by:__

XV. GENERATOR'S EPA I.D. NO.

T X D O O 7 3 3 1 1 2 7 1 1 2 13 14 15

XVI. WASTE MINIMIZATION (narrative description)

D. ADHESIVES IN SOLVENT

Texas Waste Code: 953070 EPA Waste Number: D001

An adhesive containing less solvent replaced the material generating this waste. Procedures for applying the adhesive were revised to insure the maximum amount would be removed from the drum. Presently, this waste is no longer generated.

RESULTS:	YEAR	GALLONS GENERATED
	1984	440
	1985	0

E. SPENT FLUX

Texas Waste Code: 902150 EPA Waste Number: D002

Refinements in materials and sparing use have eliminated the generation of waste from this process.

RESULTS:	YEAR	GALLONS GENERATED
	1984	55
	1985	0

F. PAINT REMOVER, STRIPPER

Texas Waste Code: 911390

EPA Waste Number: D002, D007, D008

Hangers and other metal parts associated with the painting process accumulate several coats of paint. The past procedure for removing the paint involved a paint stripper. This procedure was eliminated and replaced by a furnace which removes the paint by incineration.

RESULTS:	YEAR	GALLONS GENERATED
	1984	110
	1985	0